



Burlington WA  
Corporate Office

Bellingham WA  
Microbiology

Portland OR  
Microbiology/Chemistry

1620 S Walnut St - 98233  
800.755.9295 • 360.757.1400

805 Orchard Dr Ste 4 - 98225  
360.671.0688

9150 SW Pioneer Ct Ste W- 97070  
503.682.7802



## INORGANIC COMPOUNDS (IOC) REPORT

Client Name: Beverly Beach Improvement Club  
PO BOX 12  
Freeland, WA 98249

Reference Number: 14-05764  
Project: Beverly Beach Improvement Club

System Name: BEVERLY BEACH IMPROVEMENT CLUB  
System ID Number: 061475  
DOH Source Number: 02  
Multiple Sources:  
Sample Type: B - Before treatment  
Sample Purpose: C - Compliance  
Sample Location: S02  
County: Island

Sample Number:  
Lab Number: 046-14116  
Collect Date: 4/3/14 09:30  
Date Received: 4/3/14  
Report Date: 4/7/14  
Sampled By: Joe Waldrup  
Sampler Phone: 36-675-2457  
Released by:

DOH#	ANALYTES	RESULTS	UNITS	SRL	Trigger	MCL	Analyst	METHOD	Analyzed	COMMENT
16	<b>Other</b> ELECTRICAL CONDUCTIVITY	<b>367</b>	uS/cm	10		700	srf	SM2510 B	04/07/14	
21	<b>EPA Regulated (Secondary)</b> CHLORIDE	<b>14</b>	mg/L	0.1		250	srf	300.0	04/04/14	

**NOTES:**

SRL (State Reporting Level): indicates the minimum reporting level required by the Washington Department of Health (DOH).  
MCL (Maximum Contaminant Level) maximum permissible level of a contaminant in water established by EPA; Federal Action Levels are 0.015 mg/L for Lead and 1.3 mg/L for Copper. Sodium has a recommended limit of 20 mg/L. A blank MCL value indicates a level is not currently established.  
Trigger Level: DOH Drinking Water Response level. Systems with compounds detected in excess of this level are required to take additional samples. Contact your regional DOH office.  
ND (Not Detected): indicates that the parameter was not detected above the Specified Reporting Limit (SRL).  
An \* in front of the parameter name indicates it is not NELAP accredited but it is accredited through WSDOH or USEPA Region 10.

These test results meet all the requirements of NELAC, unless otherwise stated in writing, and relate only to these samples.  
If you have any questions concerning this report contact us at the above phone number.